



EDM TROUBLE SHOOTING


A. No Power Input




B. Discharge ----Hunting




C. Discharge unstably




D. Easy to Deposit Carbon



E. Anti fire start while start discharging



F. Trouble with DRO



G. No Processing Oil

